

Case 343 : Narrative

Case Vehicle (A): 1999 Mercury	Vehicle (B): 2001 Dodge
Type: Villager, 4-door 4x2 wagon	Type: Neon ES, 4-door sedan
Driver: 44-year-old male	Driver: 35-year-old male
CDC: 02-FDEW-3	CDC: 11-LYEW-3, 03-RBEN-1, OO-TYDO-3

SITUATION

[1](#) [2](#) On a clear day, case vehicle (A) was stopped in the northbound lane of a two-lane road, and the driver was waiting to make a left turn into a private business drive that intersects from the west. [3](#) Vehicle (B) was traveling south at a driver-estimated speed of 45 mph (72 kph) in the southbound lane of the same two-lane road. The road surface was dry, it was daylight, and the speed limit was 45 mph (72 kph). [4](#) The driver of case vehicle (A) apparently did not see vehicle (B) approaching and began to make a left turn. Case vehicle (A) entered the southbound travel lane just as vehicle (B) reached the intersection. [5](#) The driver of vehicle (B) attempted to avoid the collision by steering to the right, but was unable to keep his vehicle from being struck at an angle in the left-front fender by the front of case vehicle (A). [6](#) During the impact, the left wheel of vehicle (B) snagged the left bumper of case vehicle (A), causing vehicle (B) to rotate counterclockwise. Vehicle (B) exited the west edge of the roadway, where it struck a sign post with its right side, and then rolled over two-quarter turns with its right side leading and came to rest off the road on its roof facing south. Both vehicles were towed from the scene.

The police report indicated "C-" level injuries for the driver of case vehicle (A), who was treated at the scene by paramedics, but was not taken to a hospital. The police report indicated "C-" level injuries for the driver and the 36-week

pregnant right-front passenger of vehicle (B), who were both transported to a local hospital.

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

[7](#) Direct damage to case vehicle (A) began at the left-front bumper corner and extended 170-cm across the entire front. [8](#) The maximum crush was 58 cm at the left-front bumper corner.

[9](#) Direct damage to vehicle (B) from the impact with case vehicle (A) began at the left-front bumper corner and extended 183-cm rearward along the fender. The maximum lateral crush was 22 cm to the fender just forward of the left-front axle.

[10](#) The second impact with the sign post was to the right rear door and extended 8-cm across the door with a maximum lateral crush of 2 cm. [11](#) Rollover damage extended along the right side and roof, with a maximum crush of 7 cm to the roof.

[12](#) [13](#) [14](#) [15](#) [16](#) [17](#) [18](#) [19](#) [20](#) [21](#) Using the WinSMASH crash-reconstruction program and c-values measured for both vehicles, the following impact severities were calculated for the crash.

		Calculated Velocity Change - kph (mph)		
Vehicle	Variable	Total	Longitudinal	Latitudinal
Case Vehicle (A)	delta V	34 (21)	-22 (-14)	-26 (-16)
Vehicle (B)	delta V	50 (31)	-47 (-29)	17 (11)

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

[22](#) In the front, the left and center portions of the hood were crushed to the right and rearward. [23](#) The front bumper cover was detached from the reinforcement bar, and the bar was crushed rearward and shifted to the right. The left headlight

assembly was broken, the grille was damaged, and engine components in the left-front corner were smashed. The right headlight assembly was displaced, but the glass was not broken. The damaged hood latch was jammed, [24](#) the left hood hinge was damaged but not separated, and there [25](#) was no damage to the right hood hinge. [26](#) The rear edge of the hood was elevated but it did not contact the windshield. [27](#) There was a spider-web crack in the upper-left portion of the windshield forward of the driver seating area.

[28](#) On the left side of case vehicle (A), the left fender was crushed to the rear, deflected to the left, and pushed into the left-front wheel. [29](#) The left-front axle was damaged and the left wheelbase was decreased 7 cm. [30](#) There was no damage to the upper or lower portions of the left A-, B-, C- or D-pillars, both left-side doors were not damaged and were operable, and there was no left-side glazing damage. There was no damage to the left-rear wheel or the left quarter panel.

[31](#) [32](#) [33](#) There was no damage to the right side of case vehicle (A) and no change in the right wheelbase. [34](#) There was also no damage to the rear of case vehicle (A).

Interior

[35](#) This vehicle was equipped with driver and passenger frontal-impact airbags, which deployed during the frontal impact. [36](#) In the driver seating area, the roof, the headliner and sunvisor, and the A-pillar were not damaged. [37](#) There was a large spider-web crack in the left-center portion of the windshield. [38](#) There was no damage to the interior of the driver door. [39](#) [40](#) There was no damage to the steering wheel and no rotation of the steering column. [41](#) The plastic shield that covers the cruise control was off of its attachment on the right side of the steering wheel. [42](#) [43](#) There was pink lipstick on the center portion of the driver airbag. [44](#) There was no damage to the upper portion of the instrument panel. [45](#) The mid

portion of the instrument panel was slightly displaced and [46](#) there was a scuff mark on the left portion of the knee bolster. [47](#) [48](#) There was no damage to the floor or toe pan in the driver area, [49](#) and there was no deformation of the foot controls.

[50](#) There was no damage to the center portion of the roof or the roof header, but there was a series of longitudinal cracks in the center portion of the windshield.

[51](#) There was no damage to the center dash area or the center floor console.

[52](#) In the right-front seating area, there was no damage to the roof, the roof header, or the right A-pillar. [53](#) [54](#) There was no damage to the airbag cover or glove compartment and there was no damage to the floor, but there were some black marks on the upper portion of the passenger airbag. There were no intrusions.

OCCUPANT KINEMATICS AND INJURIES

[55](#) The 5-ft, 6-in, 180-lb, 44-year-old female driver was reportedly using the three-point belt and the steering-wheel airbag deployed. [56](#) [57](#) However, there was no clear evidence of belt use on the shoulder-belt D-ring. [58](#) The driver reportedly positioned the upper anchor point of the shoulder belt to the lowest position on the B-pillar. She was wearing eyeglasses, which were bent during the crash.

During the frontal impact, the driver moved forward and to the right relative to the vehicle interior, into the airbag and the three-point belt. She sustained a contusion to the left wrist and forearm, probably from the airbag flinging her hand and forearm into the windshield, [59](#) [60](#) as evidenced by a spider-web crack in the glass. [61](#) She sustained a contusion to the left knee, from contact with the left portion of the knee bolster, as evidenced by a scuff mark on the bolster. She sustained a contusion to the right knee from contact with the right portion of the knee bolster.

The following table [62](#) and attached drawing summarizes the injuries for the belted driver.

Occupant: Driver	Age: 44 years	Gender: Female		
Restraints: Three-point belt, steering-wheel airbag	Stature: 168 cm (5 ft, 6 in)	Mass: 82 kg (180 lb)		
Injury Description	A.I.S.	Injury Source		
—	—	Definite	Probable	Possible
Contusion, left wrist	1	—	Windshield (airbag fling)	—
Contusion, left forearm	1	—	Windshield (airbag fling)	—
Contusion, left knee	1	Knee bolster	—	—
Contusion, right knee	1	Knee bolster	—	—
Maximum A.I.S. Level	1	—	—	—
Injury Severity Score	1	—	—	—

CASE NO.: 243-01

CASE VEHICLE: 1999 Mercury


TYPE: Village, 4-door 4x4 wagon

OCCUPANT: (Driver) 44-year-old female

STATURE: 168 cm (5 ft 6 in) - MAJOR: 67 kg (148 lb)


RESISTANCE: Three-point belt, steering-wheel-riding

SEVERITY: Neck - 1 Hip - 1



Case No.: 202-20
Case/Veh. (s): 1999 Mercury
Type: Village, 4-door full wagon
Driver: 44-year-old female
Vehicle ID: 2001 Dodge Neon-ES, 4-door sedan

Weather: Clear
Road Surface: Dry
Road Construction: Asphalt
Light Condition: Daylight



Vehicle Report

General

Conditions

Variable Number and Name	Code Value	Code Description	Other Options
V206 — Urban/Rural Area	2	Rural	more
V207 — Limited Access Highway	0	No	more
V208 — Road Total Lanes	2	2 lanes	more
V209 — Intersecting Road Total Lanes	6	Parking lot/driveway	more
V210 — Road Surface Type	1	Asphalt	more
V211 — Road Defects	0	No	more
V212 — Construction Zone	0	No	more
V213 — Road Alignment Vertical Plane	1	Level	more
V214 — Road Alignment Horizontal Plane	1	Straight	more
V215 — Surface Covering	10	Dry	more
V216 — Visibility Limitation	0	None	more
V217 — Visibility Obstruction	0	None	more
V218 — Speed Limit	4	71-79 km/h .. 45 mph	more
V219 — Precipitation Type	0	None	more
V220 — Precipitation Rate	8	Not applicable	more
V221 — Temperature	9	Unknown	more
V222 — Crosswind	9	Unknown	more
V223 — Light Conditions	1	Daylight	more
V224 — Mechanical Malfunction Mention	0	No	more
V225 — Case Vehicle and Object	0	No	more

V226 — Case Vehicle Rollover	0	No	more
V227 — Case Vehicle Ran Off Roadway	0	No	more
V228 — Moving Case Vehicle/Contacted Moving Vehicle	1	Yes	more
V229 — Case Vehicle/Contacted Stopped Vehicle	0	No	more
V230 — Stopped Case Vehicle/Contactd Vehicle	0	No	more
V231 — Total Vehicles Hit By Case Vehicle	1	1 vehicle	more
V232 — Any Fire in Crash	0	No	more
V233 — Max Police Severity-PAR	1	C - Possible Injury	more
V234 — Driver Alcohol Involvement	0	Had not been drinking	more
V235 — Driver Alcohol BAC	80	Not tested	more
V236 — Driver Impairment Mention	0	No	more
V237 — Driven/Towed From Scene	2	Towed Due to Damage	more

Other Vehicle

Variable Number and Name	Code Value	Code Description	Other Options
V301 — Other Vehicle VIN	1B3ES46C51D1	—	—
V302 — Other Vehicle Manufacturer/Body Code	13228	—	—
V303 — Other Vehicle Manufacturer	132	Dodge	more
V304 — Other Vehicle Body Code	28	Intermediate 105-109.9 in. wb.	more
V305 — Other Vehicle Make/Model	0746	Neon	more
V306 — Other Vehicle Model Year	2001	—	—
V307 — Other Vehicle Mass	001164 kg	—	—
V308 — Other Vehicle Number	2	Vehicle #2	more
V309 — Other Vehicle Number of Occupants	02	—	—
V310 — Other Vehicle Traveling Speed	072 kph	—	—
V311 — Highest Police Injury Severity	1	C - Possible Injury	more
V312 — Other Vehicle Type	28	Intermediate 105-109.9 in. wb.	more
V313 — Other Vehicle Wheelbase (cm)	267 cm	—	—
V314 — Average Track Width	148 cm	—	—
V315 — Overall Length	443 cm	—	—
V316 — Overall Width (OAW)	171 cm	—	—
V317 — Front Overhang (FOH)	086 cm	—	—
V318 — Rear Overhang (ROH)	090 cm	—	—
V319 — Undeformed End Width (UEW)	144 cm	—	—
V320 — Engine Displacement	2.0 l	—	—

V321 — Engine: Number of Cylinders	04	—	—
V322 — Direct Damage Length (DDL)	999	Unknown	more
V323 — Front-End Overlap % (FEO)	99	Missing or Not applicable	more
V324 — Vehicle Overlap % (VOL)	99	Missing or Not applicable	more

Case Vehicle

General

Variable Number and Name	Code Value	Code Description	Other Options
V401 — VIN	4M2XV11T8XDJ	—	—
V402 — Manufacturer/Body Code	12211	—	—
V403 — Vehicle Manufacturer	122	Lincoln-Mercury	more
V404 — Vehicle Body Code	11	—	—
V405 — Make/Model Code	0962	Villager	more
V406 — Model Year	1999	—	—
V407 — Vehicle Mass	002320 kg	—	—
V408 — Odometer Reading	888888	—	—
V409 — Number of Occupants	01	—	—
V410 — Traveling Speed	995	Just starting up	more
V411 — Body Type	24	Van (small)	more
V412 — Stolen Vehicle	8	Not currently collected	more
V413 — Body Structure	2	Unitized	more
V414 — Transmission Type	1	Automatic	more
V415 — Transmission Lever Location	3	Column	more
V416 — Steering	1	Power	more
V417 — Brakes	1	Power	more
V418 — Brake Type	2	Disc - front wheels	more
V419 — Brake Anti-lock Device	9	Unknown	more
V420 — Air Conditioning in Vehicle	8	Not currently collected	more
V421 — Drive Type	2	Front wheel	more
V422 — Dual Rear Wheels	0	No	more

V423 — Original Restraint System Type	3	Airbag	more
V424 — Equipped With Roll Bar	0	No	more
V425 — Roof Type	4	Sun roof closed	more
V426 — Wheelbase	285 cm	—	—
V427 — Anti-lacerative Glass	0	None	more
V428 — Average Track Width	162 cm	—	—
V429 — Overall Length	494 cm	—	—
V430 — Overall Width (OAW)	190 cm	—	—
V431 — Front Overhang	101 cm	—	—
V432 — Rear Overhang	108 cm	—	—
V433 — Undeformed End Width (UEW)	170 cm	—	—
V434 — Engine Displacement	3.3 l	—	—
V435 — Engine: Number of Cylinders	06	—	—
V436 — Direct Damage Length (DDL)	170 cm	—	—
V437 — Front End Overlap % (FEO)	98	98% or more	more
V438 — Vehicle Overlap % (VOL)	98	98% or more	more

Case Vehicle

Damage

Description

Variable Number and Name	Code Value	Code Description	Other Options
V501 — Maximum Crush - Front	058 cm	—	—
V502 — Maximum Crush - Right Side	000 cm	No crush (or less than 1 cm.)	more
V503 — Maximum Crush - Rear	000 cm	No crush (or less than 1 cm.)	more
V504 — Maximum Crush - Left Side	000 cm	No crush (or less than 1 cm.)	more
V505 — Maximum Crush - Roof	000 cm	No crush (or less than 1 cm.)	more
V506 — Maximum Crush - Other	000 cm	No crush (or less than 1 cm.)	more
V507 — Are Events In Chronological Order	1	Yes	more
V508 — Event 1 Impact Location	1	On Roadway	more
V509 — Event 1 Impact Configuration	13	FRONT of case veh - SIDE of contacted Vehicle	more
V510 — Event 1 Object/Vehicle Contacted	28	Intermediate 105-109.9 in. wb.	more
V511 — Event 2 Impact Location	8	No 2nd event	more
V512 — Event 2 Impact Configuration	88	No 2nd event	more
V513 — Event 2 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V514 — Event 3 Impact Location	8	No 3rd event	more
V515 — Event 3 Impact Configuration	88	No 3rd event	more
V516 — Event 3 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V517 — Event 4 Impact Location	8	No 4th event	more
V518 — Event 4 Impact Configuration	88	No 4th event	more

V519 — Event 4 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V520 — Event 5 Impact Location	8	No 5th event	more
V521 — Event 5 Impact Configuration	88	No 5th event	more
V522 — Event 5 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V523 — Event 6 Impact Location	8	No 6th event	more
V524 — Event 6 Impact Configuration	88	No 6th event	more
V525 — Event 6 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V526 — Event 7 Impact On Road	8	No 7th event	more
V527 — Event 7 Impact Configuration	88	No 7th event	more
V528 — Event 7 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V529 — Primary CDC Case Vehicle -event Number	1	Event 1	more
V530 — Primary CDC Case Vehicle - impact speed	999	Unknown	more
V531 — Primary CDC Case Vehicle - Estimated By	1	Investigator	more
V532 — Primary CDC Case Vehicle -crush	058	—	—
V533 — Primary CDC Case Vehicle -clock #1	02	2 o'clock	more
V534 — Primary CDC Case Vehicle letter 1 #1	06	F - Front	more
V535 — Primary CDC Case Vehicle letter 2 #1	04	D - Distributed (Side or End)	more
V536 — Primary CDC Case Vehicle letter 3 #1	05	E - Everything below belt line	more
V537 — Primary CDC Case Vehicle letter 4 #1	23	W - Wide impact area	more
V538 — Primary CDC Case Vehicle Extent #1	03	Extent 3	more
V539 — Primary CDC Case Vehicle -CDC #1	02FDEW3	—	—

V541 — Primary CDC Case Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V542 — Primary CDC Case Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V543 — Primary CDC Case Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V544 — Primary CDC Case Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V545 — Primary CDC Case Vehicle Extent #2	00	Missing Data/Not applicable	more
V546 — Primary CDC Case Vehicle -CDC #2	9800000	—	—
V547 — Primary CDC Contacted Vehicle - Impact Speed	999	Unknown	more
V548 — Primary CDC Contacted Vehicle - Estimated By	1	Investigator	more
V549 — Primary CDC Contacted Vehicle -crush	022	—	—
V550 — Primary CDC Contacted Vehicle -clock #1	11	11 o'clock	more
V551 — Primary CDC Contacted Vehicle letter 1 #1	12	L - Left Side	more
V552 — Primary CDC Contacted Vehicle letter 2 #1	25	Y - Side or end (F + P or L + C)	more
V553 — Primary CDC Contacted Vehicle letter 3 #1	05	E - Everything below belt line	more
V554 — Primary CDC Contacted Vehicle letter 4 #1	23	W - Wide impact area	more
V555 — Primary CDC Contacted Vehicle Extent #1	03	Extent 3	more
V556 — Primary CDC Contacted Vehicle -CDC #1	11LYEW3	—	—
V558 — Primary CDC Contacted Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V559 — Primary CDC Contacted Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V560 — Primary CDC Contacted Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V561 — Primary CDC Contacted Vehicle letter 4 #2	00	Missing Data/Not applicable	more

V562 — Primary CDC Contacted Vehicle Extent #2	00	Missing Data/Not applicable	more
V563 — Primary CDC Contacted Vehicle -CDC #2	9800000	—	—
V564 — Secondary CDC Case Vehicle - Event No	8	Not applicable	more
V565 — Secondary CDC Case Vehicle - Impact Speed	998	Not Applicable	more
V566 — Secondary CDC Case Vehicle - Estimated By	8	Not applicable (no vehicle/no impact)	more
V567 — Secondary CDC Case Vehicle -crush	998	Not Applicable	more
V568 — Secondary CDC Case Vehicle -clock #1	98	Not Applicable	more
V569 — Secondary CDC Case Vehicle letter 1 #1	00	Missing Data/Not applicable	more
V570 — Secondary CDC Case Vehicle letter 2 #1	00	Missing Data/Not applicable	more
V571 — Secondary CDC Case Vehicle letter 3 #1	00	Missing Data/Not applicable	more
V572 — Secondary CDC Case Vehicle letter 4 #1	00	Missing Data/Not applicable	more
V573 — Secondary CDC Case Vehicle Extent #1	00	Missing Data/Not applicable	more
V574 — Secondary CDC Case Vehicle -CDC #1	9800000	—	—
V576 — Secondary CDC Case Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V577 — Secondary CDC Case Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V578 — Secondary CDC Case Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V579 — Secondary CDC Case Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V580 — Secondary CDC Case Vehicle Extent #2	00	Missing Data/Not applicable	more
V581 — Secondary CDC Case Vehicle -CDC #2	9800000	—	—
V582 — Secondary CDC Contacted Vehicle - Impact Speed	998	Not Applicable	more

V583 — Secondary CDC Contacted Vehicle - Estimated By	8	Not applicable (no vehicle/no impact)	more
V584 — Secondary CDC Contacted Vehicle -crush	998	Not Applicable	more
V585 — Secondary CDC Contacted Vehicle -clock #1	98	Not Applicable	more
V586 — Secondary CDC Contacted Vehicle letter 1 #1	00	Missing Data/Not applicable	more
V587 — Secondary CDC Contacted Vehicle letter 2 #1	00	Missing Data/Not applicable	more
V588 — Secondary CDC Contacted Vehicle letter 3 #1	00	Missing Data/Not applicable	more
V589 — Secondary CDC Contacted Vehicle letter 4 #1	00	Missing Data/Not applicable	more
V590 — Secondary CDC Contacted Vehicle Extent #1	00	Missing Data/Not applicable	more
V591 — Secondary CDC Contacted Vehicle -CDC #1	9800000	—	—
V593 — Secondary CDC Contacted Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V594 — Secondary CDC Contacted Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V595 — Secondary CDC Contacted Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V596 — Secondary CDC Contacted Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V597 — Secondary CDC Contacted Vehicle Extent #2	00	Missing Data/Not applicable	more
V598 — Secondary CDC Contacted Vehicle -CDC #2	9800000	—	—

Crash Severity

Variable Number and Name	Code Value	Code Description	Other Options
V601 — Case Vehicle Primary Impact Number	1	—	—
V602 — Primary Impact Total Delta-V	034 kph	—	—
V603 — Primary Case Vehicle Reconstructed Longitudinal Delta-V	-022 kph	—	—
V604 — Primary Case Vehicle Reconstructed Lateral Delta-V	-026 kph	—	—
V605 — Primary Case Vehicle Reconstructed Crush Energy	0284 kJ	—	—
V606 — Primary Impact Case Vehicle -reconstruction	22	Reconstructed, moderate confidence level	more
V607 — Primary Case Vehicle Reconstruction Mode	2	CDC & detailed damage	more
V608 — Primary Contacted Vehicle Reconstructed Total Delta-V	050 kph	—	—
V609 — Primary Contacted Vehicle Reconstructed Longitudinal Delta-V	-047 kph	—	—
V610 — Primary Contacted Vehicle Reconstructed Lateral Delta-V	0017 kph	—	—
V611 — Primary Contacted Vehicle Reconstructed Crush Energy	0020 kJ	—	—
V612 — Case Vehicle Secondary Impact Number	8	—	—
V613 — Secondary Case Vehicle Reconstructed Total Delta-V	888	N/A	more
V614 — Secondary Case Vehicle Reconstructed Longitudinal Delta-V	8888	—	—
V615 — Secondary Case Vehicle Reconstructed Lateral Delta-V	8888	—	—

V616 — Secondary Case Vehicle Reconstructed Crush Energy	8888	—	—
V617 — Secondary Case Vehicle Reconstruction Note	88	—	—
V618 — Secondary Case Vehicle Reconstruction Mode	8	Not applicable	more
V619 — Secondary Contacted Vehicle Reconstructed Total Delta-V	888	N/A	more
V620 — Secondary Contacted Vehicle Reconstructed Longitudinal Delta-V	8888	—	—
V621 — Secondary Contacted Vehicle Reconstructed Lateral Delta-V	8888	—	—
V622 — Secondary Contacted Vehicle Reconstructed Crush Energy	8888	—	—
V623 — Case Vehicle Primary Impact Number	1	—	—
V624 — Primary Case Vehicle Reconstructed Total EBS	034 kph	—	—
V625 — Primary Case Vehicle Reconstructed Longitudinal EBS	-022 kph	—	—
V626 — Primary Case Vehicle Reconstructed Lateral EBS	-026 kph	—	—
V627 — Primary Case Vehicle Reconstructed Crush Energy	0284 kJ	—	—
V628 — Primary Case Vehicle Reconstruction Note	22	Reconstructed, moderate confidence level	more
V629 — Primary Case Vehicle Reconstruction Mode	2	CDC & detailed damage	more
V630 — Primary Contacted Vehicle Reconstruction Total EBS	050 kph	—	—
V631 — Primary Contacted Vehicle Reconstruction Longitudinal EBS	-047 kph	—	—
V632 — Primary Contacted Vehicle Reconstruction Lateral EBS	0017 kph	—	—

V633 — Primary Contacted Vehicle Reconstruction Crush Energy	0020 kJ	—	—
V634 — Case Vehicle Secondary Impact Number	8	Not applicable	more
V635 — Secondary Case Vehicle Reconstruction Total EBS	888	N/A	more
V636 — Secondary Case Vehicle Reconstruction Longitudinal EBS	8888	—	—
V637 — Secondary Case Vehicle Reconstruction Lateral EBS	8888	—	—
V638 — Secondary Case Vehicle Reconstruction Crush Energy	8888	—	—
V639 — Secondary Case Vehicle Reconstruction Note	88	—	—
V640 — Secondary Case Vehicle Reconstruction Mode	8	Not applicable	more
V641 — Secondary Contacted Vehicle Reconstruction Total EBS	888	N/A	more
V642 — Secondary Contacted Vehicle Reconstruction Longitudinal EBS	8888	—	—
V643 — Secondary Contacted Vehicle Reconstruction Lateral EBS	8888	—	—
V644 — Secondary Contacted Vehicle Reconstruction Crush Energy	8888	—	—
V645 — Case Vehicle Reconstructed Impact Number	1	—	—
V646 — Case Vehicle Impact 1 Plane	1	Bumper	more
V647 — Case Vehicle Impact 1 Direct Damage Length [DDL]	170 cm	—	—
V648 — Case Vehicle Impact 1 Max Crush	058 cm	—	—
V649 — Case Vehicle Impact 1 Field-L	117 cm	—	—
V650 — Case Vehicle Impact 1 C1	058 cm	—	—

V651 — Case Vehicle Impact 1 C2	054 cm	—	—
V652 — Case Vehicle Impact 1 C3	044 cm	—	—
V653 — Case Vehicle Impact 1 C4	027 cm	—	—
V654 — Case Vehicle Impact 1 C5	009 cm	—	—
V655 — Case Vehicle Impact 1 C6	000 cm	No Crush	more
V656 — Case Vehicle Impact 1 +/- D	0000 cm	—	—
V657 — Case Vehicle Reconstructed Impact Number	1	—	—
V658 — Case Vehicle Impact 2 Plane	4	Above sill	more
V659 — Case Vehicle Impact 2 Direct Damage Length [DDL]	183 cm	—	—
V660 — Case Vehicle Impact 2 Max Crush	022 cm	—	—
V661 — Case Vehicle Impact 2 Field-L	191 cm	—	—
V662 — Case Vehicle Impact 2 C1	001 cm	—	—
V663 — Case Vehicle Impact 2 C2	000 cm	No Crush	more
V664 — Case Vehicle Impact 2 C3	007 cm	—	—
V665 — Case Vehicle Impact 2 C4	014 cm	—	—
V666 — Case Vehicle Impact 2 C5	016 cm	—	—
V667 — Case Vehicle Impact 2 C6	022 cm	—	—
V668 — Case Vehicle Impact 2 +/- D	0122 cm	—	—
V669 — Other Vehicle Reconstructed Impact Number	2	—	—
V670 — Other Vehicle Impact 1 Plane	8	Not applicable	more

V671 — Other Vehicle Impact 1 Direct Damage Length [DDL]	998	Not applicable	more
V672 — Other Vehicle Impact 1 Max Crush	998	Not applicable	more
V673 — Other Vehicle Impact 1 Field-L	998	Not applicable	more
V674 — Other Vehicle Impact 1 C1	998	Not applicable	more
V675 — Other Vehicle Impact 1 C2	998	Not applicable	more
V676 — Other Vehicle Impact 1 C3	998	Not applicable	more
V677 — Other Vehicle Impact 1 C4	998	Not applicable	more
V678 — Other Vehicle Impact 1 C5	998	Not applicable	more
V679 — Other Vehicle Impact 1 C6	998	Not applicable	more
V680 — Other Vehicle Impact 1 +/- D	9998	—	—
V681 — Other Vehicle Reconstructed Impact Number	2	—	—
V682 — Other Vehicle Impact 2 Plane	8	Not applicable	more
V683 — Other Vehicle Impact 2 Direct Damage Length [DDL]	998	Not applicable	more
V684 — Other Vehicle Impact 2 Max Crush	998	Not applicable	more
V685 — Other Vehicle Impact 2 Field-L	998	Not applicable	more
V686 — Other Vehicle Impact 2 C1	998	Not applicable	more
V687 — Other Vehicle Impact 2 C2	998	Not applicable	more
V688 — Other Vehicle Impact 2 C3	998	Not applicable	more
V689 — Other Vehicle Impact 2 C4	998	Not applicable	more
V690 — Other Vehicle Impact 2 C5	998	Not applicable	more

V691 — Other Vehicle Impact 2 C6	998	Not applicable	more
V692 — Other Vehicle Impact 2 +/- D	9998	—	—

Case Vehicle

Tires & Rims

Variable Number and Name	Code Value	Code Description	Other Options
V701 — Left Front Wheel Damaged	0	No	more
V702 — Right Front Wheel Damaged	0	No	more
V703 — Right Rear Wheel Damaged	0	No	more
V704 — Left Rear Wheel Damaged	0	No	more
V705 — Left Front Tire Tread Type	4	All Weather	more
V706 — Right Front Tire Tread Type	4	All Weather	more
V707 — Right Rear Tire Tread Type	4	All Weather	more
V708 — Left Rear Tire Tread Type	4	All Weather	more
V709 — Left Front Carcass Construction	3	Radial	more
V710 — Right Front Carcass Construction	3	Radial	more
V711 — Right Rear Carcass Construction	3	Radial	more
V712 — Left Rear Carcass Construction	3	Radial	more
V717 — Left Front Tire Size	P22560R16	—	—
V718 — Right Front Tire Size	P22560R16	—	—
V719 — Right Rear Tire Size	P22560R16	—	—
V720 — Left Rear Tire Size	P22560R16	—	—

Case Vehicle

Fuel, Tank, Fire

Variable Number and Name	Code Value	Code Description	Other Options
V801 — Propulsive Fuel Type	1	Gasoline	more
V802 — Main Tank Location	322	Within frame/centered laterally - within vertically	more
V803 — Main Filler Cap Location	113	Left of frame laterally - above vertically	more
V804 — Main Tank Material	9	Unknown	more
V805 — Aux Tank Type	8	Not applicable (not equipped)	more
V806 — Aux Tank Location	888	Not applicable (not equipped)	more
V807 — Aux Filler Cap Location	888	Not applicable (not equipped)	more
V808 — Aux Tank Material	8	Not applicable	more
V901 — Fuel Leakage From Crash	0	No	more
V1001 — Fire In Or On Case Vehicle	0	No	more

Case Vehicle

Exterior

Variable Number and Name	Code Value	Code Description	Other Options
V1101 — Hood Latch Released	0	No	more
V1102 — Hood Latch Damaged	1	Yes	more
V1103 — Hood Latch Jammed	1	Yes	more
V1104 — Left Hood Hinge Damaged	1	Yes	more
V1105 — Left Hood Hinge Separated	0	No	more
V1106 — Right Hood Hinge Damaged	0	No	more
V1107 — Right Hood Hinge Separated	8	Not applicable	more
V1108 — Hood Remained On Vehicle	1	Yes	more
V1109 — Rear Hood Edge Elevated	1	Yes	more
V1110 — Edge Contacted Windshield	0	No	more
V1111 — Edge Penetrated Windshield	8	Not applicable	more
V1112 — Hood Latch Location	1	Front of Vehicle	more
V1113 — Eng/Transmissn Mount Separation	0	No	more
V1114 — Steerng Column Flex Coupling	9	Unknown if equipped	more
V1115 — Steerng Column Coupling Damaged	9	Unknown	more
V1116 — Steerng Column Coupling Separated	9	Unknown	more
V1117 — Eng Comp Telescopng Unit	88	Not collected	more
V1118 — Comp Orig/Telescopd Diff	888	Not collected	more

V1119 — Left Side Body Mount Separation	8	Not applicable (unitized)	more
V1120 — Upper Left A-pillar Separation	0	No	more
V1121 — Lower Left A-pillar Separation	0	No	more
V1122 — Upper Left B-pillar Separation	0	No	more
V1123 — Lower Left B-pillar Separation	0	No	more
V1124 — Upper Left C-pillar Separation	0	No	more
V1125 — Lower Left C-pillar Separation	0	No	more
V1126 — Upper Left D-pillar Separation	0	No	more
V1127 — Lower Left D-pillar Separation	0	No	more
V1128 — Left Front Door Opening Cause	0	Door did not open	more
V1129 — Left Rear Door Opening Cause	0	Door did not open	more
V1130 — Left Front Door Jammed Closed	0	No	more
V1131 — Left Rear Door Jammed Closed	0	No	more
V1132 — Rear Door Type	2	One-way tailgate	more
V1133 — Rear Door Opening Cause	0	Door did not open	more
V1134 — Rear Door Jammed Closed	0	No	more
V1135 — Luggage Partition Damagd	8	Not applicable	more
V1136 — Spare Tire Status	8	Not collected	more
V1137 — Trailer Hitch Type	0	No hitch	more
V1138 — Trailer Type	0	No trailer	more
V1139 — Right Side Body Mount Separation	8	Not applicable (unitized)	more

V1140 — Upper Right A-pillar Separation	0	No	more
V1141 — Lower Right A-pillar Separation	0	No	more
V1142 — Upper Right B-pillar Separation	0	No	more
V1143 — Lower Right B-pillar Separation	0	No	more
V1144 — Upper Right C-pillar Separation	0	No	more
V1145 — Lower Right C-pillar Separation	0	No	more
V1146 — Upper Right D-pillar Separation	0	No	more
V1147 — Lower Right D-pillar Separation	0	No	more
V1148 — Right Front Door Opening Cause	00	Door did not open	more
V1149 — Right Rear Door Opening Cause	00	Door did not open	more
V1150 — Right Front Door Jammed Closed	0	No	more
V1151 — Right Rear Door Jammed Closed	0	No	more
V1152 — Van Rear Door Type	4	Track (sliding)-right & left side	more
V1153 — Windshield Cracked		Yes	more
V1154 — Windshield Broken	0	No	more
V1155 — Windshield Cracked or Broken by Occupant	1	Yes	more
V1156 — Bond Separation Extent	0	None	more
V1157 — Windshield Code		—	—
V1158 — Did Sun/T Roof Open	0	No	more

Case Vehicle

Steering

Column/Rim

Variable Number and Name	Code Value	Code Description	Other Options
V1201 — Steering Wheel Rim Damage	0	None	more
V1202 — Number of Steering Wheel Spokes	4	4 spokes	more
V1203 — Steering Wheel Spoke Damage	0	None	more
V1204 — Column Tilt Feature	3	Middle	more
V1205 — Column Swing-away Feature	0	Not equipped	more
V1206 — Column Telescoping Feature	0	Not equipped	more
V1207 — Wheel Energy Absorb Device	8	Not collected	more
V1208 — Wheel Ea Orig/Damaged Diff	888	Not collected	more
V1209 — Column Energy Absorb Device	88	Not collected	more
V1210 — Column Ea Orig/Comprss Diff	888	Not collected	more
V1211 — Shear Capsule Separation	888	Not collected	more
V1212 — Column Vertical Rotation	0	No apparent rotation	more
V1213 — Column Lateral Rotation	0	No apparent rotation	more
V1214 — Steering Wheel Hub Damage	0	None	more

Case Vehicle

Intrusion

Variable Number and Name	Code Value	Code Description	Other Options
V1301 — Occupant Compartment Intrusion	0	No	more
V1302 — Was Intrusion Catastrophic	8	Not applicable	more
V1303 — Intrusion Number 01	00	No Intrusion, None	more
V1304 — Intrusion 01 Occupant Space Number	00	No Intrusion, None	more
V1305 — Intrusion 01 Intruding Object	00	No Intrusion, None	more
V1306 — Intrusion 01 Assoc Event Number	0	No Intrusion, None	more
V1307 — Intrusion 01 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1308 — Intrusion 01 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1309 — Intrusion 01 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1310 — Intrusion 01 Occupant Number	00	No contact or no intrusion	more
V1311 — Intrusion 01 Injury Number	00	No injury or no intrusion	more
V1312 — Intrusion 01 Occupant Number	00	No contact or no intrusion	more
V1313 — Intrusion 01 Injury Number	99	Contact, injury unknown or data not collected	more
V1314 — Intrusion Number 02	00	No Intrusion, None	more
V1315 — Intrusion 02 Occupant Space Number	00	No Intrusion, None	more
V1316 — Intrusion 02 Intruding Object	00	No Intrusion, None	more
V1317 — Intrusion 02 Assoc Event Number	0	No Intrusion, None	more

V1318 — Intrusion 02 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1319 — Intrusion 02 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1320 — Intrusion 02 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1321 — Intrusion 02 Occupant Number	00	No contact or no intrusion	more
V1322 — Intrusion 02 Injury Number	00	No injury or no intrusion	more
V1323 — Intrusion 02 Occupant Number	00	No contact or no intrusion	more
V1324 — Intrusion 02 Injury Number	99	Contact, injury unknown or data not collected	more
V1325 — Intrusion Number 03	00	No Intrusion, None	more
V1326 — Intrusion 03 Occupant Space Number	00	No Intrusion, None	more
V1327 — Intrusion 03 Intruding Object	00	No Intrusion, None	more
V1328 — Intrusion 03 Assoc Event Number	0	No Intrusion, None	more
V1329 — Intrusion 03 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1330 — Intrusion 03 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1331 — Intrusion 03 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1332 — Intrusion 03 Occupant Number	00	No contact or no intrusion	more
V1333 — Intrusion 03 Injury Number	00	No injury or no intrusion	more
V1334 — Intrusion 03 Occupant Number	00	No contact or no intrusion	more
V1335 — Intrusion 03 Injury Number	99	Contact, injury unknown or data not collected	more
V1336 — Intrusion Number 04	00	No Intrusion, None	more
V1337 — Intrusion 04 Occupant Space Number	00	No Intrusion, None	more
V1338 — Intrusion 04	00	No Intrusion, None	more

Intruding Object			
V1339 — Intrusion 04 Assoc Event Number	0	No Intrusion, None	more
V1340 — Intrusion 04 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1341 — Intrusion 04 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1342 — Intrusion 04 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1343 — Intrusion 04 Occupant Number	00	No contact or no intrusion	more
V1344 — Intrusion 04 Injury Number	00	No injury or no intrusion	more
V1345 — Intrusion 04 Occupant Number	00	No contact or no intrusion	more
V1346 — Intrusion 04 Injury Number	99	Contact, injury unknown or data not collected	more
V1347 — Intrusion Number 05	00	No Intrusion, None	more
V1348 — Intrusion 05 Occupant Space Number	00	No Intrusion, None	more
V1349 — Intrusion 05 Intruding Object	00	No Intrusion, None	more
V1350 — Intrusion 05 Assoc Event Number	0	No Intrusion, None	more
V1351 — Intrusion 05 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1352 — Intrusion 05 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1353 — Intrusion 05 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1354 — Intrusion 05 Occupant Number	00	No contact or no intrusion	more
V1355 — Intrusion 05 Injury Number	00	No injury or no intrusion	more
V1356 — Intrusion 05 Occupant Number	00	No contact or no intrusion	more
V1357 — Intrusion 05 Injury Number	99	Contact, injury unknown or data not collected	more
V1358 — Intrusion Number 06	00	No Intrusion, None	more

V1359 — Intrusion 06 Occupant Space Number	00	No Intrusion, None	more
V1360 — Intrusion 06 Intruding Object	00	No Intrusion, None	more
V1361 — Intrusion 06 Assoc Event Number	0	No Intrusion, None	more
V1362 — Intrusion 06 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1363 — Intrusion 06 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1364 — Intrusion 06 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1365 — Intrusion 06 Occupant Number	00	No contact or no intrusion	more
V1366 — Intrusion 06 Injury Number	00	No injury or no intrusion	more
V1367 — Intrusion 06 Occupant Number	00	No contact or no intrusion	more
V1368 — Intrusion 06 Injury Number	99	Contact, injury unknown or data not collected	more
V1369 — Intrusion Number 07	00	No Intrusion, None	more
V1370 — Intrusion 07 Occupant Space Number	00	No Intrusion, None	more
V1371 — Intrusion 07 Intruding Object	00	No Intrusion, None	more
V1372 — Intrusion 07 Assoc Event Number	0	No Intrusion, None	more
V1373 — Intrusion 07 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1374 — Intrusion 07 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1375 — Intrusion 07 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1376 — Intrusion 07 Occupant Number	00	No contact or no intrusion	more
V1377 — Intrusion 07 Injury Number	00	No injury or no intrusion	more
V1378 — Intrusion 07 Occupant Number	00	No contact or no intrusion	more

V1379 — Intrusion 07 Injury Number	99	Contact, injury unknown or data not collected	more
V1380 — Intrusion Number 08	00	No Intrusion, None	more
V1381 — Intrusion 08 Occupant Space Number	00	No Intrusion, None	more
V1382 — Intrusion 08 Intruding Object	00	No Intrusion, None	more
V1383 — Intrusion 08 Assoc Event Number	0	No Intrusion, None	more
V1384 — Intrusion 08 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1385 — Intrusion 08 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1386 — Intrusion 08 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1387 — Intrusion 08 Occupant Number	00	No contact or no intrusion	more
V1388 — Intrusion 08 Injury Number	00	No injury or no intrusion	more
V1389 — Intrusion 08 Occupant Number	00	No contact or no intrusion	more
V1390 — Intrusion 08 Injury Number	99	Contact, injury unknown or data not collected	more
V1391 — Intrusion Number 09	00	No Intrusion, None	more
V1392 — Intrusion 09 Occupant Space Number	00	No Intrusion, None	more
V1393 — Intrusion 09 Intruding Object	00	No Intrusion, None	more
V1394 — Intrusion 09 Assoc Event Number	0	No Intrusion, None	more
V1395 — Intrusion 09 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1396 — Intrusion 09 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1397 — Intrusion 09 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1398 — Intrusion 09 Occupant Number	00	No contact or no intrusion	more
V1399 — Intrusion 09 Injury	00	No injury or no intrusion	more

Number			
V1400 — Intrusion 09 Occupant Number	00	No contact or no intrusion	more
V1401 — Intrusion 09 Injury Number	99	Contact, injury unknown or data not collected	more
V1402 — Intrusion Number 10	00	No Intrusion, None	more
V1403 — Intrusion 10 Occupant Space Number	00	No Intrusion, None	more
V1404 — Intrusion 10 Intruding Object	00	No Intrusion, None	more
V1405 — Intrusion 10 Assoc Event Number	0	No Intrusion, None	more
V1406 — Intrusion 10 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1407 — Intrusion 10 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1408 — Intrusion 10 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1409 — Intrusion 10 Occupant Number	00	No contact or no intrusion	more
V1410 — Intrusion 10 Injury Number	00	No injury or no intrusion	more
V1411 — Intrusion 10 Occupant Number	00	No contact or no intrusion	more
V1412 — Intrusion 10 Injury Number	99	Contact, injury unknown or data not collected	more
V1413 — Door Intrusion Number 01	88	Not Applicable	more
V1414 — Door Intrusion Number 01 Cause	8	Not applicable	more
V1415 — Door Intrusion Number 02	88	Not Applicable	more
V1416 — Door Intrusion Number 02 Cause	8	Not applicable	more
V1417 — Door Intrusion Number 03	88	Not Applicable	more
V1418 — Door Intrusion Number 03 Cause	8	Not applicable	more
V1419 — Door Intrusion 01	88	Not Applicable	more

Component			
V1420 — Door Intrusion 01 Component Damaged 1	8	Not Applicable	more
V1421 — Door Intrusion 01 Component Damaged 2	8	Not Applicable	more
V1422 — Door Intrusion 02 Component	88	Not Applicable	more
V1423 — Door Intrusion 02 Component Damaged 1	8	Not Applicable	more
V1424 — Door Intrusion 02 Component Damaged 2	8	Not Applicable	more
V1425 — Door Intrusion 03 Component	88	Not Applicable	more
V1426 — Door Intrusion 03 Component Damaged 1	8	Not Applicable	more
V1427 — Door Intrusion 03 Component Damaged 2	8	Not Applicable	more
V1428 — Door Intrusion 04 Component	88	Not Applicable	more
V1429 — Door Intrusion 04 Component Damaged 1	8	Not Applicable	more
V1430 — Door Intrusion 04 Component Damaged 2	8	Not Applicable	more

Case Vehicle

Airbag(s)

Variable Number and Name	Code Value	Code Description	Other Options
V1501 — Driver Airbag Equipped	1	Yes	more
V1502 — Driver Airbag Deployed	1	Yes	more
V1503 — Driver Airbag Condition	0	No Damage	more
V1504 — Passenger Airbag Equip	1	Yes	more
V1505 — Passenger Airbag Deployed	1	Yes	more
V1506 — Passenger Airbag Condition	0	No Damage	more
V1507 — Steering Wheel Airbag Tether	1	Yes	more
V1508 — Driver Airbag Marked By Contact	1	Yes	more
V1509 — Passenger Airbag Tether	0	No	more
V1510 — Passenger Airbag Marked By Contact	0	No	more

Case Vehicle

Interior

Variable Number and Name	Code Value	Code Description	Other Options
V1601 — Left Front Door Damaged	0	No	more
V1602 — Right Front Door Damaged	0	No	more
V1603 — Left Front Hardware Damaged	0	No	more
V1604 — Right Front Hardware Damaged	0	No	more
V1605 — Left Front Armrest Damaged	0	No	more
V1606 — Right Front Armrest Damaged	0	No	more
V1607 — Left Front Glass Damaged	0	No	more
V1608 — Right Front Glass Damaged	0	No	more
V1609 — Left Rear Door Area Damaged	0	No	more
V1610 — Right Rear Door Area Damaged	0	No	more
V1611 — Left Rear Hardware Damaged	0	No	more
V1612 — Right Rear Hardware Damaged	0	No	more
V1613 — Left Rear Armrest Damaged	0	No	more
V1614 — Right Rear Armrest Damaged	0	No	more
V1615 — Left Rear Glass Damaged	0	No	more
V1616 — Right Rear Glass Damaged	0	No	more
V1617 — Left Roof Side Rail Damaged	0	No	more
V1618 — Right Roof Side Rail Damaged	0	No	more
V1619 — Left B-pillar Damaged	0	No	more

V1620 — Right B-pillar Damaged	0	No	more
V1621 — Left C-pillar Damaged	0	No	more
V1622 — Right C-pillar Damaged	0	No	more
V1623 — Left D-pillar Damaged	0	No	more
V1624 — Right D-pillar Damaged	0	No	more
V1625 — Left Headlining Damaged	0	No	more
V1626 — Right Headlining Damaged	0	No	more
V1627 — Left Roof Structure Damaged	0	No	more
V1628 — Right Roof Structure Damaged	0	No	more
V1629 — Left T/Sun Roof Damaged	0	No	more
V1630 — Right T/Sun Roof Damaged	0	No	more
V1631 — Other Left Side Item Damagd	8	Not applicable	more
V1632 — Other Right Side Item Damagd	8	Not applicable	more
V1633 — Foot Controls Damaged	0	No	more
V1634 — Ignition Key Damaged	0	No	more
V1635 — Rear View Mirror Damaged	0	No	more
V1636 — Sunvisor/Fitting Damaged	0	No	more
V1637 — Windshield Molding Damaged	0	No	more
V1638 — Left A-pillar Damaged	0	No	more
V1639 — Right A-pillar Damaged	0	No	more
V1640 — Center Console Damaged	0	No	more
V1641 — Transmission Lever Damaged	0	No	more
V1642 — Horn/Spoke Shroud Damagd	0	No	more
V1643 — Upper Panel Damaged	0	No	more
V1644 — Mid Panel Damaged	1	Yes	more
V1645 — Lower Panel Damaged	3	No, occupant contact	more

V1646 — Ashtray Damaged	0	No	more
V1647 — Control Knob/Lever Damaged	0	No	more
V1648 — Glove Compartment Area Damaged	0	No	more
V1649 — Instruments Damaged	0	No	more
V1650 — Park Brake Release Damaged	0	No	more
V1651 — Park Brake Pedal Damaged	0	No	more
V1652 — A/C Or Upper Vent Damaged	0	No	more
V1653 — Heater Or A/C Duct Damaged	0	No	more
V1654 — Radio Damaged	0	No	more
V1655 — Other Item Damaged	1	Yes	more
V1656 — Rear Window Damaged	0	No	more
V1657 — Rear Window Header Damaged	0	No	more
V1658 — Vertical Console Damaged	0	No	more
V1659 — Roof Console Damaged	0	No	more

Case Vehicle Seats

Variable Number and Name	Code Value	Code Description	Other Options
V1701 — Driver Front Seat Type	06	Captain's chair	more
V1702 — Passenger Front Seat Type	06	Captain's chair	more
V1703 — Driver Seat Mount Type	1	Standard	more
V1704 — Passenger Seat Mount Type	1	Standard	more
V1705 — Driver Swivel Mechanism Equipped	0	No	more
V1706 — Passenger Swivel Mechanism Equipped	0	No	more
V1707 — Driver Seat Original Equipment	1	Yes	more
V1708 — Passenger Seat Original Equipment	1	Yes	more
V1709 — Driver Seat/Rear Occupant Contact	8	Not applicable	more
V1710 — Passenger Seat/Rear Occupant Contact	8	Not applicable	more
V1711 — Driver Seat Damage	0	None	more
V1712 — Passenger Seat Damage	0	None	more
V1713 — Center Front Armrest Damaged	0	No	more
V1714 — Driver Seat Rotation	0	None apparent	more
V1715 — Passenger Seat Rotation	0	None apparent	more
V1716 — Driver Seat-back Type	3	Reclining	more
V1717 — Passenger Seat-back Type	3	Reclining	more
V1718 — Driver Seat-back Lock Type	1	Manual	more

V1719 — Passenger Seat-back Lock Type	1	Manual	more
V1720 — Driver Seat-back Lock Held	1	Yes	more
V1721 — Passenger Seat-back Lock Held	1	Yes	more
V1722 — Driver Recliner Mechanism Held	1	Yes	more
V1723 — Passenger Recliner Mechanism Held	1	Yes	more
V1724 — Driver Head Restraint Type	1	Adjustable	more
V1725 — Passenger Head Restraint Type	1	Adjustable	more
V1726 — Driver Head Rest Removed	0	No	more
V1727 — Passenger Head Rest Removed	0	No	more
V1728 — Driver Head Rest Adjustment	2	Down	more
V1729 — Passenger Head Rest Adjustment	2	Down	more
V1730 — Driver Head Rest Damage	0	None	more
V1731 — Passenger Head Rest Damage	0	None	more
V1732 — Driver Seat Adjustment Type	2	Power	more
V1733 — Passenger Seat Adjustment Type	0	None (rigid)	more
V1734 — Driver Seat Adjustment Provided	3	6-way	more
V1735 — Passenger Seat Adjustment Provided	8	Not applicable	more
V1736 — Driver Seat Adjuster Damage	0	None	more
V1737 — Passenger Seat Adjuster Damage	8	Not applicable	more
V1738 — Driver Seat Adjuster Separation	8	Not applicable	more

V1739 — Passenger Seat Adjuster Separation	8	Not applicable	more
V1740 — Driver Seat Pre-crash Position	3	Rearward	more
V1741 — Passenger Seat Pre-crash Position	8	Not applicable	more
V1742 — Left Rear Seat Type	2	Folding	more
V1743 — Right Rear Seat Type	2	Folding	more
V1744 — Left Rear Seat Damaged	0	None	more
V1745 — Right Rear Seat Damaged	0	None	more
V1746 — Center Rear Armrest Damaged	1	Yes	more
V1747 — Left Rear Seat-back Left Lock Equipped	1	Yes	more
V1748 — Right Rear Seat-back Left Lock Equipped	0	No	more
V1749 — Left Rear Seat-back Left Lock Held	1	Yes	more
V1750 — Right Rear Seat-back Left Lock Held	8	Not applicable	more
V1751 — Left Rear Seat-back Right Lock Equipped	0	No	more
V1752 — Right Rear Seat-back Right Lock Equipped	1	Yes	more
V1753 — Left Rear Seat-back Right Lock Held	8	Not applicable	more
V1754 — Right Rear Seat-back Right Lock Held	1	Yes	more
V1755 — Left 3rd Seat Equipped	1	Yes	more
V1756 — Right 3rd Seat Equipped	1	Yes	more
V1757 — Left 3rd Seat Backrest Damaged	0	No	more
V1758 — Right 3rd Seat Backrest Damaged	0	No	more

V1759 — Left 3rd Seat Cushion Damaged	0	No	more
V1760 — Right 3rd Seat Cushion Damaged	0	No	more
V1761 — Rear Head Restraints	1	Equipped	more

Case # 343: Occupant # 1; Injury # 1

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	01	Injury #1	more
V2102 — 1st Prob Contact Area	12	Windshield	more
V2103 — 2nd Prob Contact Area	87	Air cushion skin "airbag"	more
V2104 — Primary OIC -body Region	23	Wrist/hand	more
V2105 — Primary OIC -aspect	12	Left	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	WLCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 343: Occupant # 1; Injury # 2

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	02	Injury #2	more
V2102 — 1st Prob Contact Area	12	Windshield	more
V2103 — 2nd Prob Contact Area	87	Air cushion skin "airbag"	more
V2104 — Primary OIC -body Region	18	Forearm	more
V2105 — Primary OIC -aspect	12	Left	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	RLCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 343: Occupant # 1; Injury # 3

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	03	Injury #3	more
V2102 — 1st Prob Contact Area	48	Knee restraint	more
V2103 — 2nd Prob Contact Area	00	No Contact/not applicable	more
V2104 — Primary OIC -body Region	11	Knee	more
V2105 — Primary OIC -aspect	12	Left	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	KLCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 343: Occupant # 1; Injury # 4

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	04	Injury #4	more
V2102 — 1st Prob Contact Area	48	Knee restraint	more
V2103 — 2nd Prob Contact Area	00	No Contact/not applicable	more
V2104 — Primary OIC -body Region	11	Knee	more
V2105 — Primary OIC -aspect	18	Right	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	KRCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 343: Occupant # 1

Variable Number and Name	Code Value	Code Description	Other Options
V2001 — Occupant Number	01	Occupant #1	more
V2002 — Occupant Role At 1st Impact	1	Motor vehicle driver	more
V2003 — Occupant Position -row	1	1st row	more
V2004 — Occupant Position -lateral	1	Left	more
V2005 — Occupant Position -posture	10	Sitting on seat	more
V2006 — Occupant Age In Years	44	—	—
V2007 — Occupant Age In Months	25	25 months or older	more
V2008 — Occupant Mass	082 kg	—	—
V2009 — Occupant Height	168 cm	—	—
V2010 — Occupant Sex	2	Female	more
V2011 — Occupant Treatment/Mortality	00	None	more
V2012 — Injury Severity Score	01	ISS 1	more
V2013 — Non-impact Med Condition	0	None	more
V2014 — Police Injury Severity	1	C - Possible injury	more
V2015 — Active Restraint System	3	Both lap belt and shoulder harness	more
V2016 — Active Restraint Usage	3	Both lap belt and shoulder harness	more
V2017 — Passive Restraint System	1	Air bag installed	more
V2018 — Passive Restraint Usage	2	Air bag deployed	more
V2019 — Child Seat Type	88	Not applicable (adult or older child)	more
V2020 — Occupant Ejection Degree	0	None	more
V2021 — Occupant Ejection Area	98	Not applicable (not ejected)	more

V2022 — Highest OIC Severity	1	Minor	more
V2023 — Head Restraint Available	1	Equipped	more
V2024 — Occupant Eyewear	1	Glasses	more
V2025 — Source of Occupant Info	0	Interview	more

RETENEZ VOTRE ENFANT
LES DISPOSITIFS DE SECURITE A L'INTERIEUR DU VEHICULE





CHANGE

OFF









NO
PASSING
AHEAD

DO
NOT
PASS



































1997-1998
402
415
425
435
445
455
465
475
485
495
505
515
525
535
545
555
565
575
585
595
605
615
625
635
645
655
665
675
685
695
705
715
725
735
745
755
765
775
785
795
805
815
825
835
845
855
865
875
885
895
905
915
925
935
945
955
965
975
985
995
1005
1015
1025
1035
1045
1055
1065
1075
1085
1095
1105
1115
1125
1135
1145
1155
1165
1175
1185
1195
1205
1215
1225
1235
1245
1255
1265
1275
1285
1295
1305
1315
1325
1335
1345
1355
1365
1375
1385
1395
1405
1415
1425
1435
1445
1455
1465
1475
1485
1495
1505
1515
1525
1535
1545
1555
1565
1575
1585
1595
1605
1615
1625
1635
1645
1655
1665
1675
1685
1695
1705
1715
1725
1735
1745
1755
1765
1775
1785
1795
1805
1815
1825
1835
1845
1855
1865
1875
1885
1895
1905
1915
1925
1935
1945
1955
1965
1975
1985
1995
2005
2015
2025
2035
2045
2055
2065
2075
2085
2095
2105
2115
2125
2135
2145
2155
2165
2175
2185
2195
2205
2215
2225
2235
2245
2255
2265
2275
2285
2295
2305
2315
2325
2335
2345
2355
2365
2375
2385
2395
2405
2415
2425
2435
2445
2455
2465
2475
2485
2495
2505
2515
2525
2535
2545
2555
2565
2575
2585
2595
2605
2615
2625
2635
2645
2655
2665
2675
2685
2695
2705
2715
2725
2735
2745
2755
2765
2775
2785
2795
2805
2815
2825
2835
2845
2855
2865
2875
2885
2895
2905
2915
2925
2935
2945
2955
2965
2975
2985
2995
3005
3015
3025
3035
3045
3055
3065
3075
3085
3095
3105
3115
3125
3135
3145
3155
3165
3175
3185
3195
3205
3215
3225
3235
3245
3255
3265
3275
3285
3295
3305
3315
3325
3335
3345
3355
3365
3375
3385
3395
3405
3415
3425
3435
3445
3455
3465
3475
3485
3495
3505
3515
3525
3535
3545
3555
3565
3575
3585
3595
3605
3615
3625
3635
3645
3655
3665
3675
3685
3695
3705
3715
3725
3735
3745
3755
3765
3775
3785
3795
3805
3815
3825
3835
3845
3855
3865
3875
3885
3895
3905
3915
3925
3935
3945
3955
3965
3975
3985
3995
4005
4015
4025
4035
4045
4055
4065
4075
4085
4095
4105
4115
4125
4135
4145
4155
4165
4175
4185
4195
4205
4215
4225
4235
4245
4255
4265
4275
4285
4295
4305
4315
4325
4335
4345
4355
4365
4375
4385
4395
4405
4415
4425
4435
4445
4455
4465
4475
4485
4495
4505
4515
4525
4535
4545
4555
4565
4575
4585
4595
4605
4615
4625
4635
4645
4655
4665
4675
4685
4695
4705
4715
4725
4735
4745
4755
4765
4775
4785
4795
4805
4815
4825
4835
4845
4855
4865
4875
4885
4895
4905
4915
4925
4935
4945
4955
4965
4975
4985
4995
5005
5015
5025
5035
5045
5055
5065
5075
5085
5095
5105
5115
5125
5135
5145
5155
5165
5175
5185
5195
5205
5215
5225
5235
5245
5255
5265
5275
5285
5295
5305
5315
5325
5335
5345
5355
5365
5375
5385
5395
5405
5415
5425
5435
5445
5455
5465
5475
5485
5495
5505
5515
5525
5535
5545
5555
5565
5575
5585
5595
5605
5615
5625
5635
5645
5655
5665
5675
5685
5695
5705
5715
5725
5735
5745
5755
5765
5775
5785
5795
5805
5815
5825
5835
5845
5855
5865
5875
5885
5895
5905
5915
5925
5935
5945
5955
5965
5975
5985
5995
6005
6015
6025
6035
6045
6055
6065
6075
6085
6095
6105
6115
6125
6135
6145
6155
6165
6175
6185
6195
6205
6215
6225
6235
6245
6255
6265
6275
6285
6295
6305
6315
6325
6335
6345
6355
6365
6375
6385
6395
6405
6415
6425
6435
6445
6455
6465
6475
6485
6495
6505
6515
6525
6535
6545
6555
6565
6575
6585
6595
6605
6615
6625
6635
6645
6655
6665
6675
6685
6695
6705
6715
6725
6735
6745
6755
6765
6775
6785
6795
6805
6815
6825
6835
6845
6855
6865
6875
6885
6895
6905
6915
6925
6935
6945
6955
6965
6975
6985
6995
7005
7015
7025
7035
7045
7055
7065
7075
7085
7095
7105
7115
7125
7135
7145
7155
7165
7175
7185
7195
7205
7215
7225
7235
7245
7255
7265
7275
7285
7295
7305
7315
7325
7335
7345
7355
7365
7375
7385
7395
7405
7415
7425
7435
7445
7455
7465
7475
7485
7495
7505
7515
7525
7535
7545
7555
7565
7575
7585
7595
7605
7615
7625
7635
7645
7655
7665
7675
7685
7695
7705
7715
7725
7735
7745
7755
7765
7775
7785
7795
7805
7815
7825
7835
7845
7855
7865
7875
7885
7895
7905
7915
7925
7935
7945
7955
7965
7975
7985
7995
8005
8015
8025
8035
8045
8055
8065
8075
8085
8095
8105
8115
8125
8135
8145
8155
8165
8175
8185
8195
8205
8215
8225
8235
8245
8255
8265
8275
8285
8295
8305
8315
8325
8335
8345
8355
8365
8375
8385
8395
8405
8415
8425
8435
8445
8455
8465
8475
8485
8495
8505
8515
8525
8535
8545
8555
8565
8575
8585
8595
8605
8615
8625
8635
8645
8655
8665
8675
8685
8695
8705
8715
8725
8735
8745
8755
8765
8775
8785
8795
8805
8815
8825
8835
8845
8855
8865
8875
8885
8895
8905
8915
8925
8935
8945
8955
8965
8975
8985
8995
9005
9015
9025
9035
9045
9055
9065
9075
9085
9095
9105
9115
9125
9135
9145
9155
9165
9175
9185
9195
9205
9215
9225
9235
9245
9255
9265
9275
9285
9295
9305
9315
9325
9335
9345
9355
9365
9375
9385
9395
9405
9415
9425
9435
9445
9455
9465
9475
9485
9495
9505
9515
9525
9535
9545
9555
9565
9575
9585
9595
9605
9615
9625
9635
9645
9655
9665
9675
9685
9695
9705
9715
9725
9735
9745
9755
9765
9775
9785
9795
9805
9815
9825
9835
9845
9855
9865
9875
9885
9895
9905
9915
9925
9935
9945
9955
9965
9975
9985
9995
10005
10015
10025
10035
10045
10055
10065
10075
10085
10095
10105
10115
10125
10135
10145
10155
10165
10175
10185
10195
10205
10215
10225
10235
10245
10255
10265
10275
10285
10295
10305
10315
10325
10335
10345
10355
10365
10375
10385
10395
10405
10415
10425
10435
10445
10455
10465
10475
10485
10495
10505
10515
10525
10535
10545
10555
10565
10575
10585
10595
10605
10615
10625
10635
10645
10655
10665
10675
10685
10695
10705
10715
10725
10735
10745
10755
10765
10775
10785
10795
10805
10815
10825
10835
10845
10855
10865
10875
10885
10895
10905
10915
10925
10935
10945
10955
10965
10975
10985
10995
11005
11015
11025
11035
11045
11055
11065
11075
11085
11095
11105
11115
11125
11135
11145
11155
11165
11175
11185
11195
11205
11215
11225
11235
11245
11255
11265
11275
11285
11295
11305
11315
11325
11335
11345
11355
11365
11375
11385
11395
11405
11415
11425
11435
11445
11455
11465
11475
11485
11495
11505
11515
11525
11535
11545
11555
11565
11575
11585
11595
11605
11615
11625
11635
11645
11655
11665
11675
11685
11695
11705
11715
11725
11735
11745
11755
11765
11775
11785
11795
11805
11815
11825
11835
11845
11855
11865
11875
11885
11895
11905
11915
11925
11935
11945
11955
11965
11975
11985
11995
12005
12015
12025
12035
12045
12055
12065
12075
12085
12095
12105
12115
12125
12135
12145
12155
12165
12175
12185
12195
12205
12215
12225
12235
12245
12255
12265
12275
12285
12295
12305
12315
12325
12335
12345
12355
12365
12375
12385
12395
12405
12415
12425
12435
12445
12455
12465
12475
12485
12495
12505
12515
12525
12535
12545
12555
12565
12575
12585
12595
12605
12615
12625
12635
12645
12655
12665
12675
12685
12695
12705
12715
12725
12735
12745
12755
12765
12775
12785
12795
12805
12815
12825
12835
12845
12855
12865
12875
12885
12895
12905
12915
12925
12935
12945
12955
12965
12975
12985
12995
13005
13015
13025
13035
13045
13055
13065
13075
13085
13095
13105
13115
13125
13135
13145
13155
13165
13175
13185
13195
13205
13215
13225
13235
13245
13255
13265
13275
13285
13295
13305
13315
13325
13335
13345
13355
13365
13375
13385
13395
13405
13415
13425
13435
13445
13455
13465
13475
13485
13495
13505
13515
13525
13535
13545
13555
13565
13575
13585
13595
13605
13615
13625
13635
13645
13655
13665
13675
13685
13695
13705
13715
13725
13735
13745
13755
13765
13775
13785
13795
13805
13815
13825
13835
13845
13855
13865
13875
13885
13895
13905
13915
13925
13935
13945
13955
13965
13975
13985
13995
14005
14015
14025
14035
14045
14055
14065
14075
14085
14095
14105
14115
14125
14135
14145
14155
14165
14175
14185
14195
14205
14215
14225
14235
14245
14255
14265
14275
14285
14295
14305
14315
14325
14335
14345
14355
14365
14375
14385
14395
14405
14415
14425
14435
14445
14455
14465
14475
14485
14495
14505
14515
14525
14535
14545
14555
14565
14575
14585
14595
14605
14615
14625
14635
14645
14655
14665
14675
14685
14695
14705
14715
14725
14735
14745
14755
14765
14775
14785
14795
14805
14815
14825
14835
14845
14855
14865
14875
14885
14895
14905
14915
14925
14935
14945
14955
14965
14975
14985
14995
15005
15015
15025
15035
15045
15055
15065
15075
15085
15095
15105
15115
15125
15135
15145
15155
15165
15175
15185
15195
15205
15215
15225
15235
15245
15255
15265
15275
15285
15295
15305
15315
15325
15335
15345
15355
15365
15375
15385
15395
15405
15415
15425
15435
15445
15455
15465
15475
15485
15495
15505
15515
15525
15535
15545
15555
15565
15575
15585
15595
15605
15615
15625
15635
15645
15655
15665
15675
15685
15695
15705
15715
15725
15735
15745
15755
15765
15775
15785
15795
15805
15815
15825
15835
15845
15855
15865
15875
15885
15895
15905
15915
15925
15935
15945
15955
15965
15975
15985
15995
16005
16015
16025
16035
16045
16055
16065
16075
16085
16095
16105
16115
16125
16135
16145
16155
16165
16175
16185
16195
16205
16215
16225
16235
16245
16255
16265
16275
16285
16295
16305
16315
16325
16335
16345
16355
16365
16375
16385
16395
16405
16415
16425
16435
16445
16455
16465
16475
16485
16495
16505
16515
16525
16535
16545
16555
16565
16575
16585
16595
16605
16615
16625
16635
16645
16655
16665
16675
16685
16695
16705
16715
16725
16735
16745
16755
16765
16775
16785
16795
16805
16815
16825
16835
16845
16855
16865
16875
16885
16895
16905
16915
16925
16935
16945
16955
16965
16975
16985
16995
17005
17015
17025
17035
17045
17055
17065
17075
17085
17095
17105
17115
17125
17135
17145
17155
17165
17175
17185
17195
17205
17215
17225
17235
17245
17255
17265
17275
17285
17295
17305
17315
17325
17335
17345
17355
17365
17375
17385
17395
17405
17415
17425
17435
17445
17455
17465
17475
17485
17495
17505
17515
17525
17535
17545
17555
17565
17575
17585
17595
17605
17615
17625
17635
17645
17655
17665
17675
17685
17695
17705
17715
17725
17735
17745
17755
17765
17775
17785
17795
17805
17815
17825
17835
17845
17855
17865
17875
17885
17895
17905
17915
17925
17935
17945
17955
17965
17975
17985
17995
18005
18015
18025
18035
18045
18055
18065
18075
18085
18095
18105
18115
18125
18135
18145
18155
18165
18175
18185
18195
18205
18215
18225
18235
18245
18255
18265
18275
18285
18295
18305
18315
18325
18335
18345
18355
18365
18375
18385
18395
18405
18415
18425
18435
18445
18455
18465
18475
18485
18495
18505
18515
18525
18535
18545
18555
18565
18575
18585
18595
18605
18615
18625
18635
18645
18655
18665
18675
18685
18695
18705
18715
18725
18735
18745
18755
18765
18775
18785
18795
18805
18815
18825
18835
18845
18855
18865
18875
18885
18895
18905
18915
18925
18935
18945
18955
18965
18975
18985
18995
19005
19015
19025
19035
19045
19055
19065
19075
19085
19095
19105
19115
19125
19135
19145
19155
19165
19175
19185
19195
19205
19215
19225
19235
19245
19255
19265
19275
19285
19295







farmers
ABZ
UV
key
won't
start



2-8630

WC
9-13
SL

282









PARKED
A B 2
W/ KEY
WANT
STRT











⚠ WARNING	⚠ AVERTISSEMENT
 <p>DEATH or SERIOUS INJURY can occur - Children 12 and under can be killed by the air bag. - The seat is not for use with a child seat. - Do not use the seat for anything other than its intended use. - Do not use the seat for anything other than its intended use. - Do not use the seat for anything other than its intended use.</p>	<p>Risque de MORT ou DE BLESSURES GRAVES - Les enfants de 12 ans et moins peuvent être tués par le coussin gonflable. - Le siège n'est pas à utiliser avec un siège d'enfant. - Ne pas utiliser le siège pour autre chose que son usage prévu. - Ne pas utiliser le siège pour autre chose que son usage prévu. - Ne pas utiliser le siège pour autre chose que son usage prévu.</p>















LIPSTICK

615





CHANGE

OFF











WINDSHIELD REPAIR SERVICE

NO PARKING

2-4-15

2-4-15

2-4-15







WARNING

24504
594
WU
F3H
THOW
T1-t2









01128





